



Hot Work

Standard Operating Procedures

Access Control, Fire & Security Systems Department

Cleveland State University
Access Control & Security Systems Department
Hot Work Procedures

The Cleveland State University Hot Work Standard Operating Procedures have been developed to comply with requirements set forth in the Occupational Safety and Health Administration (OSHA) General Industry Standards for Welding Cutting and Brazing (29 CFR 1910 Subpart Q)

Hot Work Procedures Defined

The following operating procedures refer to the performance of activities described as ‘hot work’ on the campus of Cleveland State University. Any “hot work” performed on campus outside of a workshop specifically designated for such work requires a permit. **“Hot work” is defined as any heat, fire or spark-producing activity such as welding, flame cutting or grinding.** Blank Hot Work Permit Forms shall be provided to applicable areas upon request by the Office of Access Control & Security Systems.

Who needs a Hot Work Permit?

Permits are required of both university employees and outside contracted employees as part of building renovations, maintenance and repair

Cleveland State University

Designated Individuals Authorized to Issue Hot Work Permits

EMERGENCIES - Call 9-1-1 – Ask for CSU Police Dispatch

Patrick Westropp

Fire Inspector
Plant Services 230
Office: 216.687.3842
Cell: 216.256.5572

Dan Ivan

Fire Inspector
Plant Services 230
Office: 216.687.5238

Carolyn Pelletiere

Environmental Health & Safety
Coordinator
Office: 216.687.5388

Robert Howerton

Environmental Health & Safety
Officer
Plant Services 233
Office: 216.687.3715
Cell: 216.276.4324

EMERGENCIES - Call 216-687-2020 CSU Campus Safety Dispatch